


PROCESS FLOW DIAGRAM FOR 10T/H POULTRY FEED PLANT(Computer)



NO.	Name	NO.	Name	NO.	Name	NO.	Name
101	Dumping Hopper	201	Prebin for hammer mill	308	Manual Adding Hopper	413	Rotary Screener
102, 207, 307, 602	Pulse Filter	202, 302, 402, 502	Level Indicator	310	Double Shaft Mixer	501	Bin for finished products
103, 208, 306, 408, 601	Fan	203, 309, 503	Slide Gate	401	Prebin for pellet mill	604	Air compressor
104, 105, 312, 504	Chain Conveyor	204, 311, 403	Buffer Hopper	404	Pellet Mill	605	Air tank
106, 110, 210, 313, 412	Bucket Elevator	205	Impeller Feeder	405	Airlosed feeder	606	Air dryer
107	Drum Precleaner	206	Hammer Mill	406	Counterflow Cooler	607	Liquid Adding Machine
108, 314	Tubular Magnet	209	Screw Conveyor	407	Muffler	608	Accessories
109, 315, 414	Three-way discharger	301	Batching Bins	409	Cyclone	609	Liquid Scale
111	Powder cleaning screener	303, 304	Proportioning screws	410, 603	Airlock		
112, 211	Rotary Pipe Distributor	305	Proportioning Scale	411	Crumbler		

STEEL STRUCTURE OF FEED MILL COMPUTER CONTROL CENTER AIR COMPRESSING SYSTEM LIQUID ADDING SYSTEM TRUCK SCALE ELECTRICAL HOIST TRANSFORMER CENTER BOILER AND ACCESSORIES

ENGINEERING NAME	SUBITEM NAME	10T/H POULTRY FEED PLANT	DIAGRAM NO	DATE